Touch Screen Packaging Weighing Controller

4.3 inch touch screen for single scale

Instruction Manual

V1.1

Modification date: 2021-1-16

Contents

1	SUMM	ARY	2
	1.1 Produ	UCT INTRODUCTION	2
	1.2 SAFET	TY TIPS	. 3
	1.3 TECH	NICAL PARAMETERS AND DIMENSIONS	. 3
	1.4 I/O		.5
2	INTERFA	ACE AND OPERATION METHOD	.6
	2.1 Weigi	HING INTERFACE	.6
	2.2 Param	METER DISPLAY AND SETTING	. 7
	2.2.1	System parameter	7
	2.2.2	Formula parameter	.8
	2.2.3	APP parameter	.9
	2.2.4	I/O parameter	10
	2.2.5	COMM parameter	10
	2.2.6	Query data1	10
	2.2.7	System calibration	11
3	SUPPL	EMENTARY NOTES 1	2
	3.1 modb	US COMMUNICATION PROTOCOL 1	12
	3.2 Other	R COMMUNICATIONS 1	14
	3.2.1	Active sending protocol	14
	3.3 Proci	ESS DESCRIPTION 1	14
	3.4 OTHE	R FUNCTIONS	15
	3.5 MOD	BUS RTU COMMUNICATION EXAMPLES 1	15

1 Summary

1.1 Product introduction

Thank you for choosing our products. Before using this product, please read this manual carefully to make this product work to the maximum extent.

This product integrates the control part and touch screen operation part, with friendly interface and convenient operation.

This product uses 24 bit $\sum -\triangle ADC$ chip, and the analog signal of bridge load cell is converted into digital signal. It also have 4 DI and 8 DO,1 sensor inputs, In addition to the weighing signal transmission function, it can also achieve a large number of control functions.

Suitable for 18-30vdc power supply system.24 V power supply is recommended.

This product also has the function of sensor circuit detection, that is, when the sensor is not connected or the sensor is faulty (including the wiring falling off, etc.), the corresponding alarm will be given [effective when only one sensor is connected to each channel].

Product features:

1. Signal acquisition, control and touch screen operation are integrated, and the operation is convenient and fast;

- 2. It can prevent RFI / EMI interference and has strong EMC characteristics;
- 3. 21-26v DC supply;
- High speed 24 bit ∑-△ADC sampling, each channel more than
 500Hz sampling, control output and sampling interval synchronization;
- 5. Complete sensor fault detection function, such as signal overrun, module sampling fault, sensor line connection fault, etc;
- 6. Complete communication interface, Standard RS 232 and 485,Optional CAN, etc;
- 7. Mass storage, which can store more than 300000 pieces of data.

1.2 Safety tips



- The instrument has anti-interference design. Be sure to ground the instrument reliably and separate it from the AC power supply ground wire;
- 2. Do not use in flammable gas environment;
- 3. Avoid direct sunlight;

1.3 Technical parameters and dimensions

Measurement signal -20mV~20mV, Each can drive 6 load cells with 350 ohm

Sampling frequency	500Hz
Accuracy	III level
Resolution	1/500000
DI/DO	4 DI, 8 DO, Low level active
Communication	rs 232,rs 485。Optional with CAN
Nonlinearity	0.005%FS
Power	21-26V DC. Sensor voltage 5V.
Weight	About 0.7kg
Dimensions	135. 9*88. 5*24. 5
Opening size	130. 5*83
Power waste	< 10W
Temperature	-20 [~] +65℃

1.4 I/O



Touch Screen Weighing Controller

Power	DC 24V
Sensitivity	1-4 mV / V
Accuracy	Level



CAL CAH B B G G KX X30

Explain

1: X40 is DI terminal, valid for COM,NPN type photoelectric junction; PRO is the programming button, Press and hold this button, and then power on the instrument to enter the download program;

2: X50 is DO terminal, The wiring is shown in the figure above;

3: X30 is a communication extension interface (CAL/CAH is CAN, TX/RX/G is RS232, A/B is

RS485);

4: X11 is loadcell interface;

5: X10 is the power interface, DC + and DC - to connect the DC power, and 24 V DC is

recommended; PE is shielded interface;

6: VD + must be connected to the positive power supply of relay.

2 Interface and operation method

2.1 Weighing interface

	Controller			U	Jnit
	SP1 SP	2 SP3	FII	a dis	
AUTO		00	0()0	Real
	PCS:	00000	SP3	00000	EDIT
START	TOT: 00000 Formula: 00000 NAME: 00000		FIN	00	000
CLAMP	CAL	PARA		CLEAR	Login

1. AUTO, It is used to make the controller switch between manual and automatic state. Double click to switch to manual state;

2. START, In the automatic state, it is used to start the packaging process. Double click to stop;

3. Other operations need to log in first. The password is 123. When the indicator light on the login button turns green, all parameters can be operated. Enter password 0, login will be cancelled.

4. EDIT is used to manually correct the SP3 ° CLEAR used to clear the TOT, PCS, etc., need to log in to operate.

System selection Set the unit, decimal System point, system time etc. Set the SP1, SP2, SP3 Formula [Variable] and other parameters Set the process time, APP working mode, etc. Set I/O, COMM. and I/0related test functions Recovery Back Query Password:123456

2.2 Parameter display and setting

2.2.1 System parameter



Name	Default(Range)	Describe		
Unit	g(g,kg,t,N,kN,lb)			
Dec.Point	1(0-4)	Decimal point setting		
DIV	0(0-5)	Division. 0:1 1:2 2:5 3:10 4:20 5:50。		

Filter 1 10(0-19)		The larger the value is, the better the filtering effect is, but the weight display lags behind.For SP1 and SP2.
Filter 2 15(0-19)		The larger the value is, the better the filtering effect is, but the weight display lags behind.For weight display and SP3.
Para. No.		The register number of the parameter can be queried in 3.1.(the number should bigger than 1000)
Para. Value		The parameter value corresponding to the register number.
Dyn.Range 0.01(0.00-99.99)		When this value is greater than 0, it starts to judge whether it is stable.
Dyn.Time	0.30(0.00-9.99)	During this time, if the weight change is within the stable range, it will be stable.
Zero Range 0.00(0.00-99.99)		When the value is greater than 0, the auto zero operation is performed.
Zero Time	1.00(0.00-9.99)	During this time, if the weight is within the range and is stable all the time, it will be automatically set to zero. Continuous stability is set to zero only once.

2.2.2 Formula parameter

	FORMULA	
TRGT:		
SP1:		
SP2:		
SP3:		
NULL:		
Formula No.:		
Formula Name:		Back

- 1: When the target value is set to 0, the scale will not start;
- 2: The current weight is greater than zero zone, the scale does not start;

2.2.3 APP parameter

APP				
Start delay:	LooseBag delay:			
Open delay:	APP:			
SP1 OFF delay:	Zero before fill:			
SP2 OFF delay:	Fill mode:			
All OFF delay:	Flow drop time:			
D/C ON delay:				
D/C OFF delay:	Back			

Name	Default(Range)	Describe	
Start delay	2.50(0-500.00)	The time delay before starting feeding is set to zero automatically	
		after this time delay.	
Open delay	0.30((0-500.00)	After opening the SP1,SP2,SP3 door, it starts to weight after this delay	
SP1 OFF delay	0.50((0-500.00)	When closing SP1, delay to compare the weight.	
SP2 OFF delay	0.50((0-500.00)	When closing SP2, delay to compare the weight.	
All OFF delay	1.00((0-500.00)	When closing All SP, delay to compare the weight.	
D/C ON delay	2.00((0-500.00)	Delay the time to open the discharge door.	
		When the weight is less than the NULL value, the discharge door will	
D/C OFF delay	0.50((0-500.00)	be closed with delay	
LooseBag delay	0.00(0.00-99.99)	Delay this time to release the bag after closing the discharge door.	
		0: HOP],The hopper mode with a bag for weight increase;	
		1:unused.	
400	0(0,4)	2:BAG,The bag mode working independently.	
APP	0(0-4)	3:Subtraction	
		4:WeightOn Run,The weighing table on the container starts	
		automatically.	
Fill Mode	0(0-1)	0, Meanwhile; 1, Order。	
Zero before fill	1(0-99)	After this start number is set to zero.	
Flow drop time -	0.0(0.0.10.0)	When the setting is greater than 0, the flow mode is adopted to	
Flow drop time	0.0(0.0-10.0)	adjust the drop.	

2.2.4 I/O parameter

AD		I/O COMM		
I1: I2: I3: I4:	o1: o2: o3: o4: o5: o6:	Ix Functions 1. Start 2. Stop 3. Clamp 4. Zero 5. Pause 6. STT 7. Stock L 8. Stock H	ox I 1. Clamp 2. SP1 3. SP2 4. SP3 5. Disc 6. Finis 7. Belt 8. DEV	Functions 9.Fill
	08:	I/O Test [When it sto	ps]	Back

2.2.5 COMM parameter

In the I/O parameter interface, click COMM button to enter the communication setting interface.

2.2.6 Query data

	Data	query		
No.	Time	Target	Wei	IIP
				01
				DOWN
				20111
				Input No.
				Current
CLEAR	СОРҮ	PRINT		Back

2.2.7 System calibration

CalibrationAD:ZeroZero:ZeroCoefficient:FullReal:FullBack

Press the CAL button at the main screen.

Zero: Calibrate the zero

Full: Input the weight on the current scale.

3 Supplementary notes

3.1 modbus Communication protocol

This protocol	is compatible v	vith TCP address.	The data is 32-bit.
---------------	-----------------	-------------------	---------------------

名称	缺省值(范围)	描述	寄存器
Weight		Read: Weight	1
		Write 0, zero calibration	
		Write more than 0, weight calibration	
AD		Read: AD	3
Result		Read:Packaging results	5
State		See Note 1 after the table	9
Unused			11
DI State			13
DO State			15
Total 1	0-100000000	Low value of total	17
Total 2	0-100000000	High value of total。Total=Total 2*100000000+Total 1	19
PCS			21
Loadcell'state		AD fault。0,1bit,The excitation line may break; 2 bit,	23
		overflow,Maybe the sensor is broken or the signal wire	
		is broken; 3 bit,Module error.	
Para. No.		The register number of the parameter can be queried in	997
		3.1.(the number should bigger than 1000)	
Para. Value		The parameter value corresponding to the register	999
		number.	
Zero			1001
Coefficient			1009
Filter 1	10(0-19)	The larger the value is, the better the filtering effect is,	1019
		but the weight display lags behind.For SP1 and SP2.	
Filter 2	15(0-19)	The larger the value is, the better the filtering effect is,	1021
		but the weight display lags behind.For weight display	
		and SP3.	
DIV	0(0-5)	0:1 1:2 2:5 3:10 4:20 5:50.	1023
Dyn.Range	0.01(0.00-99.99)	When this value is greater than 0, it starts to judge	1025
		whether it is stable.	
Dun Time	0 30/0 00-0 99)	During this time, if the weight change is within the	1027
Dyn.mine	0.30(0.00-9.99)	stable range, it will be stable.	
Crean Dance	0 00(0 00-99 99)	When this value is greater than 0, creep correction is	1029
	0.00(0.00-33.33)	carried out.	

Creep Time	10.00(0.00-99.99)	In this time, the weight change is in the Creep Range and is stable, so the creep correction is carried out.	1031
Zero Range	0.00(0.00-99.99)	When the value is greater than 0, the auto zero operation is performed.	1033
Zero Time	1.00(0.00-9.99)	During this time, if the weight is within the range and is stable all the time, it will be automatically set to zero. Continuous stability is set to zero only once.	1035
Unit	g(g,kg,t,N,kN,lb)		1067
Dec.Point	1(0-4)	Decimal point setting	1069
Formula	0(0-49)		1075
Null	100(1-999999)	Threshold value used to judge empty scale bucket	1077
Target	5000(1-999999)		1085
SP1	2000(1-999999)		1093
SP2	1000(1-999999)		1101
SP3	500(1-999999)		1109
Start delay	2.50(0-500.00)	The time delay before starting feeding is set to zero automatically after this time delay.	1117
Open delay	0.30((0-500.00)	After opening the SP1,SP2,SP3 door, it starts to weight after this delay	1119
SP1 OFF delay	0.50((0-500.00)	When closing SP1, delay to compare the weight.	1121
SP2 OFF delay	0.50((0-500.00)	When closing SP2, delay to compare the weight.	1123
All OFF delay	1.00((0-500.00)	When closing All SP, delay to compare the weight.	1125
D/C ON delay	0.00-99.99s	Delay the time to open the discharge door.	1127
D/C ON delay 2	2.00((0-500.00)	No comparison after opening the discharge door	1129
D/C OFF delay	0.50((0-500.00)	When the weight is less than the NULL value, the discharge door will be closed with delay	1131
LooseBag delay	0.00(0.00-99.99)	Delay this time to release the bag after closing the discharge door.	1133
I1 Functions		See 2.2.4 interface parameters for details	1157
I2 Functions			1159
13 Functions	0(0-99)		1161
I4 Functions			1163
I5 Functions			1165
o1 Functions		See 2.2.4 interface parameters for details	1173
o2 Functions			1175
o3 Functions			1177
O4 Functions			1179
O5 Functions	0(0-99)		1181
O6 Functions			1183
O7 Functions			1185
O8 Functions			1187
Zero before fill	1(0-99)	After this start number is set to zero.	1213

Fill Mode	0(0-1)	0, Meanwhile; 1, Order。	1215
Stop packages	0(0-999999)	Stop the machine after passing the package	1221
A Point close time	0.00(0.00-99.99)	The closing time and opening time should be greater	1225
Point open time	0.00(0.00-99.99)	than 0 when the SP3 inching function is needed.	1233
Supplementary	0(0-1)	0, OFF: 1 ON	1241
materials	-(/		
Supplementary	0.00(0.00.00.00)	SP3 ON time when supplementary materials.	1243
materials Time	0.00(0.00-99.99)		
A Deviation	0(0-999999)	The weight error is acceptable within this range.	1245
Total set	0(0-999999999)	If the setting is greater than 0, the cumulative control	1253
		mode is adopted. Reach the set cumulative shutdown	
Flow drop time	0.0(0.0-10.0)s	When the setting is greater than 0, the flow mode is	1255
		adopted to adjust the drop.	
High		The current weight is greater than High	1329
	100(1-999999)	value, the scale does not start. Set to 0,	
		the function fails	

Explain 1: .00bit Run; .01bit Pack; .02bit SP1; .03bit SP2; .04bit SP3; .05bit Final; .06bit Discharge;

3.2 Other communications

3.2.1 Active sending protocol

START	[+/-]	DATA	DEC[0-3]	XOR	END
0x02	0x2B/0X2D	6 chars	0x30-0x33	2 chars	0xFF

1:The data is transmitted in ASCII code. For example, if 1234 is displayed, hexadecimal 30 31 32 33 34 will be passed.

2:The XOR operation is performed on all data[not contain a start character] before the XOR check bit, and can get a byte of data, Then the byte is converted into two ASCII codes. For example, the computed check is 0x4a, and the corresponding hexadecimal ASCII is 34 41.

3.3 Process description

Bag weight: Power on \rightarrow Pack input \rightarrow Pack Out \rightarrow Start \rightarrow Delay then Zero \rightarrow SP1/SP2/SP3 Out

→ Open delay → Achieve (Target-SP1)SP1 OFF → SP1 OFF delay → Achieve (Target-SP2)SP2 OFF → SP2 OFF delay → Start SP3 flow check(02-029) or weight check(Target-SP1) → All OFF delay → Fill finish → Loose bag → delay → Weight below null → delay and reset pack out → wait next loop;

Hopper weight: Power on \rightarrow Start \rightarrow Delay then Zero \rightarrow SP1/SP2/SP3 Out \rightarrow Open delay \rightarrow Achieve (Target-SP1)SP1 OFF \rightarrow SP1 OFF delay \rightarrow Achieve (Target-SP2)SP2 OFF \rightarrow SP2 OFF delay \rightarrow Start SP3 flow check(02-029) or weight check(Target-SP1) \rightarrow All OFF delay \rightarrow Fill finish \rightarrow Pack input \rightarrow Discharge output \rightarrow Weight below null \rightarrow Delay \rightarrow Discharge OFF \rightarrow Delay \rightarrow wait next loop $\downarrow \rightarrow$ Delay \rightarrow Pack OFF

Subtraction: Power on \rightarrow Check whether the material weight is greater than 1.2 * target value (otherwise, the alarm will be reset after the weight is greater than 1.2 * target value) \rightarrow Pack input \rightarrow Pack Out \rightarrow Start \rightarrow Open delay \rightarrow Achieve (Target-SP1)SP1 OFF \rightarrow SP1 OFF delay \rightarrow Achieve (Target-SP2)SP2 OFF \rightarrow SP2 OFF delay \rightarrow Start SP3 flow check(02-029) or weight check(Target-SP1) \rightarrow All OFF delay \rightarrow Fill finish \rightarrow Pack Out OFF \rightarrow Delay \rightarrow wait next loop

3.4 Other functions

If you need the function of Ethernet network, please contact the manufacturer in advance. The configuration and testing tools of Ethernet can be obtained from the manufacturer.

3.5 MODBUS RTU Communication examples

The address of the company adopts Siemens system address description rules, and the actual instruction is sent. The instruction is hexadecimal, and the address needs to be reduced by 1.

Master to slave read data operation

The host reads 32 bits of register 1, the order is: 01 03 00 00 00 02 C4 0B Slave Function number Data address Data number CRC check Then the MCU receives the data, calculates CRC according to the data, and judges whether the data is correct, if the data is correct, The back data order like this: 01 03 04 00 01 E2 40 E2 A3 Slave **CRC** Check Function number Data number data

The four hex data are converted to decimal, which is 123456.

Master to slave write data operation

The host write 32 bits of register 1, the order is

15 / 8

Write the	e weight 12345	56, the order	is:			
01	10	00 00	00 02	04	00 01 E2 40	EB 3F
Slave	Function No.	Data Addr.	Reg.No.	Char No.	Data	CRC Check
Do Zero	, the order is:					
01	10	00 00	00 02	04	00 00 00 00	0 F3 AF
Back:						
01	10	00 00	00 02	41	C8	
Slave	Function No.	Data Addr.	Reg.No.	CRC	Check	

Modbus RTU CRC check code calculation method

```
//modbus CRC16
publicvoid CRC16Calc(byte[] dataBuff, int dataLen)
{
    int CRCResult = 0xFFFF;
    if (dataLen < 2)
    {
        return;
   }
    for
       (int i = 0; i < (dataLen - 2); i++)
    {
          CRCResult = CRCResult ^ dataBuff[i];
           for (int j = 0; j < 8; j++)
            {
                   if ((CRCResult & 1) == 1)
```

```
CRCResult = (CRCResult >> 1) ^ 0xA001;
else CRCResult >>= 1;
}
dataBuff[dataLen - 1] =Convert.ToByte(CRCResult >> 8);
dataBuff[dataLen - 2] =Convert.ToByte(CRCResult & 0xff);
```

}